

Furniture Restoration

Pictures taken
from the Web

Regency Sofa



Dressing Table



Mahogany Chair



Furniture Restoration

Taken from Website of



Dutch & Duchess

18th Century Louis XVI Period Metamorphic Sideboard Mahogany

Problems:

Construction warped because of moist damage. Marquetry inlay damaged and partly missing. Drawers worn, back and bottom split.

Metamorphic Sideboard



Stages of repair



Stages of repair



Finished



Restoration on a Tripod Table



Tripod table with broken foot



Close-up of the broken foot

Restoration on a Tripod Table



Close-up of the broken leg



Missing section rebuilt



Front view of the repair



Shaping to match the original profile

Restoration on a Tripod Table



Viewed from the other side



Viewed from the front



The finished piece, restored



The finished piece, restored